
	<b>INSPECTION REPORT</b>	<b>Report Date:</b>	Nov 01 2008	<b>Overall Result</b>
		<b>Booking No.:</b>		
		<b>Inspection No.:</b>		
		<b>Client Name:</b>		<b>6 Pages</b>

Vendor/Supplier:		<b>Defect</b>	<b>Actual found</b>	<b>Allowed limit</b>
		Critical		
Factory Name:		Major		
		Minor		
Inspection Date:	Nov 01 2008			


<b>A.GENERAL</b>	
From: Wenzhou Trust Testing & Inspection Co., Ltd.(TTC) Contact: Vicky Lin Tel: 0086-577-88915592 Fax: 0086-577-88915610 Email:ttctest@gmail.com Inspector Name(s):COKE	To: Contact: Tel: Fax: Email: Copy To:
Service Performed: FRI	Ref. Sample Received Date: N/A


<b>B.REMARKS</b>	
1.	Approval sample was provided for this inspection.
2.	There was no vent hole and warning words on the ploy-bag.
3.	We checked 450pcs product and found 34 defects, details please check sheet and photos.
4.	The inspector random 8pcs product to TTC lab for testing.





	<b>INSPECTION REPORT</b>	<b>Report Date:</b>	Nov 01 2008	<b>Overall Result</b>
		<b>Booking No.:</b>		
		<b>Inspection No.:</b>		
		<b>Client Name:</b>		<b>6 Pages</b>


Total check pieces:		450PCS
Description		Defect number
1.	puckering at sleeve opening/armhole	7
2.	wavy front bottom hem	6
3	slant front placket	2
4	poor front placket shape	1
5.	oil stain	1
6.	broken stitches at hem	1
7.	hole	1
8.	laddering (dropped stitches)	1
9.	broken yarn	1
10.	untrimmed thread ends	5
11.	color fly	3
12.	dirty mark	3
13.	exposed color stitches	2
<b>Total Found:</b>		34













For the details, please see the following attached photos.

		
Photo 1) Export carton	Photo 2) Shipping mark	Photo 3) Side mark

	<b>INSPECTION REPORT</b>	<b>Report Date:</b>	Nov 01 2008	<b>Overall Result</b>
		<b>Booking No.:</b>		
		<b>Inspection No.:</b>		
		<b>Client Name:</b>		<b>6 Pages</b>

		
<p>Photo 4) Open carton</p>	<p>Photo 5) Individual package</p>	<p>Photo 6) Product</p>
<p>Photo 7) Main label</p>	<p>Photo 8) Hangtag and fish accessory</p>	<p>Photo 9) hangtag</p>
		
<p>Photo 10) fish accessory</p>	<p>Photo 11) "made in China" label</p>	<p>Photo 12) "made in China" label</p>
		
<p>Photo 13) care label</p>	<p>Photo 14) tissue paper</p>	<p>Photo 15) printing on polybag</p>

	<b>INSPECTION REPORT</b>	<b>Report Date:</b> Nov 01 2008	<b>Overall Result</b>
		<b>Booking No.:</b>	
		<b>Inspection No.:</b>	<b>6 Pages</b>
		<b>Client Name:</b>	

		
<p>Photo 16) color fly yarn</p>	<p>Photo 17) broken yarn</p>	<p>Photo 18) untrimmed thread ends</p>
		
<p>Photo 19) dirty mark</p>	<p>Photo 20) slant front placket</p>	<p>Photo 21) untrimmed thread ends</p>
		
<p>Photo 22) puckering</p>	<p>Photo 23) exposed color stitches</p>	<p>Photo 24) puckering</p>
		
<p>Photo 25) puckering</p>	<p>Photo 26) wavy front bottom hem</p>	<p>Photo 27) slant front placket</p>


	<b>INSPECTION REPORT</b>	<b>Report Date:</b>	Nov 01 2008	<b>Overall Result</b> <b>N/A</b>
		<b>Booking No.:</b>	N/A	
		<b>Inspection No.:</b>		<b>6 Pages</b>
		<b>Client Name:</b>		



Photo 28) poor front placket shape



Photo 29) untrimmed thread ends



Photo 30) puckering



Photo 31) puckering



Photo 32) slant front placket



Photo 33) hole



Photo 34) puckering



Photo 35) oil stain



Photo 36) broken stitches



Photo 37) laddering (dropped stitches)



Photo 38) wavy front bottom hem



Photo 39) wavy front bottom hem


	<b>INSPECTION REPORT</b>	<b>Report Date:</b>	Nov 01 2008	<b>Overall Result</b>
		<b>Booking No.:</b>		
		<b>Inspection No.:</b>		
		<b>Client Name:</b>		<b>6 Pages</b>

		
Photo 40) wavy front bottom hem	Photo 41) wavy front bottom hem	Photo 42) fly yarn

<b>Approval by:</b>	Vicky Lin
<b>Date:</b>	Nov 01 2008