
	INSPECTION REPORT	Report Date:	Mar 31. 2008	Overall Result PASS
		Booking No.:	N/A	
		Inspection No.:	2006-01	6 pages
		Client Name:		

Vendor/Supplier:		Defect	Actual found	Allowed limit
		Critical	0	0
Factory Name:	N/A	Major	0	10
		Minor	12	14
Inspection Date:	Begin: date- Mar 31 .2008 Time-10:10	End: date- Mar 31. 2008 Time-16:00		

	Product Description:3 piece desk set									
P.O.No.	Item/Style/Sku	Ordered Quantity		Supplied Quantity		Packed Quantity		Unpacked Quantity		Barcode
		Units	Ctns	Units	Ctns	Units	Ctns	Units	Ctns	
2006-01	ILMSDK	6000	55	6000	55	4950	45	1050	10	N/A
Total:	N/A	6000	55	6000	55	4950	45	1050	10	N/A

INSPECTION RESULT SUMMARY					
	PASS	FAIL	PENDING	N/A	REMARK
PRODUCT TYPE	X				
WORKMANSHIP	X				
ON-SITE TESTS	X				
PACKING&ASSORTMENT	X				
LABELING,PRINGTING&MARKING	X				


A.GENERAL	
From: Wenzhou Trust Testing & Inspection Co., Ltd.(TTC) Contact: Vicky Lin Tel: 0086-577-88915592 Fax: 0086-577-88915610 Email:ttctest@gmail.com Inspector Name(s):FRANK	
Service Performed: FRI	Ref. Sample Received Date: Mar 18. 2008
Total qty of Export Ctns:55CTNS	Number of Export Cartons Opened for Inspection: 8CTNS
List of Export Carton Numbers Opened:	NO CARTON NUMBER

	INSPECTION REPORT	Report Date:	Mar 31. 2008	Overall Result
		Booking No.:	N/A	
		Inspection No.:	2006-01	
		Client Name:		6 pages

B.REMARKS	
1.	Approval sample was provided for this inspection.
2.	No side mark on carton.
3.	A shipment sample was kept by TTC.

C. INSPECTION CRITERIA					
Inspection Standard:		ANSI/ASQC Z1.4(formerly known as MIL-STD-105)			
Inspection Level-Workmanship/Visual:		G II	AQL-Critical Defectives:	0	
			AQL-Major Defectives:	2.5	
Sample Size-Workmanship/Visual:		200pcs	AQL-Minor Defectives:	4.0	
			AQL-Other:	N/A	
Description			Critical	Major	Minor
1.	Dirt mark on ring				6
2.	Glue mark on barrel				4
3.	Scratch mark on magnifying				2
Total Found:			0	0	12
Total Allowed:			0	10	14
Result:			PASS	PASS	PASS

D. ON-SITE TESTS				
	Check Points		Findings	Result
1.	Description:	Re-mailer box size	18*9*2.5cm 18*9*2.5cm 18*9*2.5cm	PASS
	Sample Size:	3Pcs		
2.	Description:	Carton drop test	NO FAILURE	PASS
	Sample Size:	1 Carton		

	INSPECTION REPORT	Report Date:	Mar 31. 2008	Overall Result PASS
		Booking No.:	N/A	
		Inspection No.:	2006-01	6 pages
		Client Name:		

E. PACKING & ASSORTMENT								
Packing								
Cartons	Quantity	Carton Size (cm)					Weight (Kgs)	Result
		Length	Width	Height	Other	Client Tolerance		
Export/Outer (given)	110	48	38	29	N/A	N/A	21.4	PENDING
Export/Outer (actual)	110	49	38.5	29	N/A		21.5	
Assortment								
No. of Cartons Checked		No. of Cartons Failed		Findings / Comments			Result	
1		0		NO FAILURE			Pass	
Export Carton Details								
New or Used	NEW		Sealing	Opaque Gummed Tape		NO		
Material	PAPER CARD			Transparent Gummed Type		YES		
# Corrugated Paper Plies	5 PLIES			Paper Type		NO		
Fastening- Metal Staples	NO		Strapping	Nylon Band		YES		
Individual package: One piece keytag, & one piece pen & one piece magnifying packed by air bubble then packed into a re-mailer box								
Result: PASS								

F. LABELING / PRINTING / MARKING			
Name	Location	Findings / Comments	Result
Logo	Product body	No failure	PASS
Result: PASS			

For the details, please see the following attached photos.








	INSPECTION REPORT	Report Date:	Mar 31. 2008	Overall Result PASS
		Booking No.:	N/A	
		Inspection No.:	2006-01	6 pages
		Client Name:		

Photo 1	Photo 2	Photo 3
		
Approval sample	Approval sample	Label
Photo 4	Photo 5	Photo 6
		
Approval sample	Carton	Shipping mark
Photo 7	Photo 8	Photo 9
		
Packed into carton	Re-mailer box	Details











	INSPECTION REPORT	Report Date:	Mar 31. 2008	Overall Result
		Booking No.:	N/A	
		Inspection No.:	2006-01	
		Client Name:		6 pages

Photo 10	Photo 11	Photo 12
		
Details	Packed into box	Air bubble packaging
Photo 13	Photo 14	Photo 15
		
Product	Wright testing	Dirt mark on ring
Photo 16	Photo 17	Photo 18
		
Dirt mark on ring	Dirt mark on ring	Glue mark on barrel




	INSPECTION REPORT	Report Date:	Mar 31. 2008	Overall Result PASS
		Booking No.:	N/A	
		Inspection No.:	2006-01	
		Client Name:		6 pages

Photo 19	Photo 20	Photo 21
		N/A
Glue mark on barrel	Scratch mark on magnifying	N/A

Approval by:	Vicky Lin
Date:	Mar 31. 2008